

# PRODUCT CHANGES: DATA UPDATE

## DATA UPDATE

Part number	Manufacturer	Model	Body type	Year	Remarks
BW019B1/D1	BMW	3 Series (E46)	Cabriolet	04/2004-12/2007	Not in program anymore, no replacement
BW019B1/D1	BMW	3 Series (E46)	Compact	03/2001-02/2005	Not in program anymore, no replacement
BW019B1/D1	BMW	3 Series (E46)	Coupé	02/1999-07/2006	Not in program anymore, no replacement
BW019B1/D1	BMW	3 Series (E46)	Estate	09/1999-08/2005	Not in program anymore, no replacement
BW019B1/D1	BMW	3 Series (E46)	Saloon	04/1998-12/2004	Not in program anymore, no replacement
FR011DB	Ford	Mondeo III	Estate	01/2001-05/2007	Not in program anymore, no replacement
SY003BB	Ssang Yong	Rexton	SUV	01/2002-09/2017	Not in program anymore, replaced by SY003BL
SB002BB	Subaru	Forester	SUV	01/1997-12/2002	Not in program anymore, no replacement
SB002BB	Subaru	Impreza	5 drs hatchback	01/1997-12/2000	Not in program anymore, no replacement
SB002BB	Subaru	Impreza	Saloon	01/1993-12/1996	Not in program anymore, no replacement
SB002BB	Subaru	Legacy III	Estate	01/1997-12/2003	Not in program anymore, no replacement
SB002BB	Subaru	Legacy III	Saloon	01/1997-09/2009	Not in program anymore, no replacement
VW146B1/D1	Volkswagen	Tiguan eHybrid	SUV	02/2021-	Vehicle integration
VW190B1/H1	Volkswagen	Tiguan eHybrid	SUV	02/2021-	Vehicle integration
VW146B1/D1	Volkswagen	T-Roc	SUV	11/2017-	Also suitable for the 03/2022- facelift models
VW190B1/H1	Volkswagen	T-Roc	SUV	11/2017-	Also suitable for the 03/2022- facelift models
VW146B1/D1	Volkswagen	T-Roc	Cabriolet	11/2017-	Also suitable for the 03/2022- facelift models
VW190B1/H1	Volkswagen	T-Roc	Cabriolet	11/2017-	Also suitable for the 03/2022- facelift models



[www.ecs-electronics.com](http://www.ecs-electronics.com)



[Newsletter archive](#)