

PRODUCT CHANGES: DATA UPDATE

DATA UPDATE (1/1)

Part number	Manufacturer	Model	Body type	Year	Remarks
AU060B1/D1	Audi	A7	5 drs hatchback	01/2015-01/2018	
AU060B1/D1	Audi	A7 Sportback	5 drs hatchback	01/2015-01/2018	
BW028B1/D1	BMW	6 Series GT (G32)	5 drs hatchback	11/2017-	Integrated in existing towbar wiring kit
BW028B1/D1	BMW	X3 (G01)	SUV	11/2017-	Integrated in existing towbar wiring kit
FI044BX/DX	Fiat	500X	SUV	02/2015-12/2017	
FR104B1/D1	Ford	EcoSport	SUV	02/2018-	Integrated in existing towbar wiring kit
HN862BX/DX	Honda	Civic X	5 drs hatchback	03/2017-	
HN862BX/DX	Honda	Civic X	Saloon	07/2017-	
JG009F1/H1	Jaguar	E-Pace (X540)	SUV	01/2018-	
KI099BL/DL	Kia	Niro	SUV	10/2016-	
KI099BL/DL	Kia	Niro PHEV	SUV	10/2017-	
KI099BL/DL	Kia	Stinger	Saloon	10/2017-	
MZ123BH/DH	Mazda	2	5 drs hatchback	01/2015-	Also suitable for the 03/2017- model
MZ123BH/DH	Mazda	CX-3	SUV	06/2015-	Also suitable for the 06/2017- model
MB080B1/D1/H1	Mercedes	C-Class (A205)	Cabriolet	07/2016-	Integrated in existing towbar wiring kit
PE071B1/D1	Opel	Grandland X	SUV	10/2017-	Not for vehicles without permanent feed (+30) under the driver seat
ROV014B/L	Rover	45	3 drs hatchback	01/2000-12/2003	Not in program anymore, alternative: ROV003B/L
ROV014B/L	Rover	416	3 drs hatchback	01/1995-01/1999	Not in program anymore, alternative: ROV003B/L
SY020BX/DX	Ssang Yong	Rexton	SUV	10/2017-	
VW146B1/D1	Volkswagen	Golf VII Hybrid	5 drs hatchback	08/2013-	Integrated in existing towbar wiring kit
VW190B1/H1	Volkswagen	Golf VII Hybrid	5 drs hatchback	08/2013-	Integrated in existing towbar wiring kit
VOL004B	Volvo	850	Estate Saloon	01/1992-01/1997	Not in program anymore
VL048FX/HX	Volvo	XC40 (536)	5 drs hatchback	03/2018-	Integrated in existing towbar wiring kit

Newsletter archive: www.ecs-electronics.nl/newsletter-archive



www.ecs-electronics.com

