

PRODUCT CHANGES: DATA UPDATE (1/2)

CATEGORY	PARTNUMBER	MANUFACTURER	MODEL	BODY TYPE	YEAR
Nouveau produit	FI055FH/HH	Opel	Movano C	Chassis	01/2022-
	MZ178BX/DX	Mazda	CX-60	SUV	04/2022-
Intégré au faisceau existant	DS001B1/D1	Opel	Astra Sports Tourer	Break	02/2022-
	MB107FX/HX	Mercedes	C-Class	Break	06/2021-
	MB107FX/HX	Mercedes	C-Class	Limousine	06/2021-
	MB107FX/HX	Mercedes	C-Class All-Terrain	Break	11/2021-
	MB107FX/HX	Mercedes	C-Class Hybrid	Break	06/2021-
	MB107FX/HX	Mercedes	C-Class Hybrid	Limousine	06/2021-
L'usage limité	MZ153BX/DX	Mazda	CX-5	SUV	05/2017-12/2022
Non plus dans notre program, remplacement MB107HX	MB106HX	Mercedes	C-Class	Break	06/2021-
	MB106HX	Mercedes	C-Class	Limousine	06/2021-
	MB106HX	Mercedes	C-Class All-Terrain	Break	11/2021-
	MB106HX	Mercedes	C-Class Hybrid	Break	06/2021-
	MB106HX	Mercedes	C-Class Hybrid	Limousine	06/2021-



www.ecs-electronics.com



PRODUCT CHANGES: DATA UPDATE (2/2)

CATEGORY	PARTNUMBER	MANUFACTURER	MODEL	BODY TYPE	YEAR
Non plus dans notre program, remplacement TO297DH	TO313DL	Toyota	Yaris	5 Porte	09/2020-
	TO313DL	Toyota	Yaris Hybrid	5 Porte	09/2020-
	TO241DL	Citroën	C1 II	3/5 Porte	07/2014-
	TO241DL	Peugeot	108	3/5 Porte	07/2014-
	TO241DL	Toyota	Aygo	3/5 Porte	05/2014-
Non plus dans notre program, il n'y a pas une remplacement	CT046D1	Citroën	C5 III	Limousine	10/2008-07/2017
	LR005DH	Landrover	Freelander II	SUV	10/2012-02/2021
	LR009BH	Landrover	Discovery Sport	SUV	02/2015-08/2019
	PE020DL	Peugeot	307 CC	Cabriolet	10/2003-04/2008
	PE025DL	Peugeot	1007	MPV	07/2005-01/2009
	TO162DH	Toyota	Prius	5 Porte	08/2003-03/2009

[Newsletter archive](#)



www.ecs-electronics.com

