

# PRODUCT CHANGES: DATA UPDATE

## DATA UPDATE

Part number	Manufacturer	Model	Body type	Year	Remarks
DA009BB/DL	Dacia	Sandero	5 drs hatchback	10/2012-12/2016	
DA009BB/DL	Dacia	Sandero Stepway	5 drs hatchback	10/2012-12/2016	
FI046BX/DX	Fiat	Tipo	Saloon	06/2016-	Not in program anymore
MZ072BH	Mazda	CX-7	SUV	01/2009-	
MB076B1/D1/H1	Mercedes	E-Class (S212)	Estate	09/2009-09/2016	
MB083BX/DX/HX	Mercedes	E-Class (S213)	Estate	10/2016-	For vehicles without prepared connector
MB084B1/H1	Mercedes	GLS (X166)	SUV	03/2016-	
MT115BH/DH	Mitsubishi	Outlander	SUV	10/2012-	Also suitable for 2017 model
RN124BB/DH	Renault	Grand Scenic	MPV	05/2013-11/2016	
RN124BB/DH	Renault	Scenic	MPV	05/2013-10/2016	
SK025B1/H1	Skoda	Rapid	5 drs htachback	06/2015-	
SK025B1/H1	Skoda	Rapid Spaceback	5 drs hatchback	06/2015-	
SK024B1/H1	Skoda	Superb	Estate Saloon	08/2015-	
SY012BH/HH	Ssang Yong	XLV	SUV	05/2016-	
TO245BH/HH	Toyota	C-HR	SUV	10/2016-	
TO163BB/DL	Toyota	Prius	5 drs hatchback	04/2009-10/2015	

TECHNICAL SUPPORT



Newsletter archive: [www.ecs-electronics.nl/newsletter-archive](http://www.ecs-electronics.nl/newsletter-archive)

[www.ecs-electronics.com](http://www.ecs-electronics.com)

