

# PRODUCT CHANGES: DATA UPDATE

## DATA UPDATE (1/1)

| Part number | Manufacturer | Model           | Body type       | Year            | Remarks                      |
|-------------|--------------|-----------------|-----------------|-----------------|------------------------------|
| VW146B1/D1  | Skoda        | Karoq Scout     | SUV             | 02/2019-        | Added to existing wiring kit |
| VW190B1/H1  | Skoda        | Karoq Scout     | SUV             | 02/2019-        | Added to existing wiring kit |
| VW146B1/D1  | Skoda        | Karoq Sportline | SUV             | 02/2019-        | Added to existing wiring kit |
| VW190B1/H1  | Skoda        | Karoq Sportline | SUV             | 02/2019-        | Added to existing wiring kit |
| VW146B1/D1  | Skoda        | Scala           | 5 drs hatchback | 04/2019-        | Added to existing wiring kit |
| VW190B1/H1  | Skoda        | Scala           | 5 drs hatchback | 04/2019-        | Added to existing wiring kit |
| VL026B1/D1  | Volvo        | S60 II          | Saloon          | 01/2011-03/2019 |                              |

TECHNICAL  
SUPPORTNewsletter archive: [www.ecs-electronics.nl/newsletter-archive](http://www.ecs-electronics.nl/newsletter-archive)[www.ecs-electronics.com](http://www.ecs-electronics.com)